



Total Quality. Assured.  
TEST REPORT



中国认可  
国际互认  
检测  
TESTING  
CNAS L0220

Number: GZHT90869286

Date: Mar 18, 2019

Applicant: CORTINA N.V.  
MEERSBLOEM-MELDEN 42,  
9700 OUDENAARDE,BELGIUM  
Attn: PETER DE MEZURE

Sample Description:

Four and a half (4.5) pairs of submitted samples said to be Steel plates.

Standard : ASTM F2413-18  
Size : US 8  
Buyer's Name : CORTINA N.V.  
Ref. No : BESTBOY/BESTRUN/ORION/TITAN/BOTANIC/GOBI  
Brand : SAFETYJOGGER  
Manufacturer : CORTINA N.V.  
Colour : BLACK  
Vendor : --  
Supplier : --  
P.O. No. : --  
Ref. : Steel plate used for BESTBOY/BESTRUN/ORION/TITAN/BOTANIC/GOBI  
Country Of Origin : --  
Goods Exported To : Belgium/U.S.A.  
Date Received/Date Test Started: Mar 05, 2019  
Date Final Information Confirmed: --

Test Result Please Refer To Attached Page(S).

Should you have any query on this report, you may contact at [gzfootwear@intertek.com](mailto:gzfootwear@intertek.com)

Authorized By:  
For Intertek Testing Services Shenzhen Ltd.  
Guangzhou Branch



Guiliang Dong  
Senior Lab Manager



jo / nicoleho

**Intertek Testing Services Shenzhen Ltd. Guangzhou Branch**

深圳天祥质量技术服务有限公司广州分公司

Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801,  
No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China  
广州经济技术开发区科学城彩频路7号之二第1-8层02房、01房101、  
E201、E301、E401、E501、E601、E701、E801  
Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou  
Economic & Technological Development District, Guangzhou,  
China  
中国广州经济技术开发区开发大道235号恒运大厦3楼  
Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730



1 Puncture Resistance Footwear (PR) (ASTM F2412-18a, 11, Conditioned At 22°C And 50% RH For 24 h And Testing Performed At The Same Conditions)

		<u>ASTM F2413-18 Requirement</u>	<u>Pass/Fail</u>
Left:	The Test Pin Did Not Penetrate Beyond The Face Of The Material Nearest The Foot Before 1200 N	Min. 1200 N (*)	Pass
Right:	The Test Pin Did Not Penetrate Beyond The Face Of The Material Nearest The Foot Before 1200 N	Min. 1200 N (*)	Pass
Right:	The Test Pin Did Not Penetrate Beyond The Face Of The Material Nearest The Foot Before 1200 N	Min. 1200 N (*)	Pass

Remark: \* = The Test Pin Does Not Visually Penetrate Beyond The Face Of The Material Nearest The Foot.

2 Corrosion Resistance For Puncture Resistant Plates (ASTM F2412-18a, 11.8 & ASTM B117, 5% NaCl Solution For 24 Hours)

		<u>ASTM F2413-18 Requirement</u>	<u>Pass/Fail</u>
Left:	No Sign Of Corrosion	*	Pass
Left:	No Sign Of Corrosion	*	Pass
Right:	No Sign Of Corrosion	*	Pass

Remark: \* = No Sign Of Corrosion, De-lamination, Or Deterioration.

3 Flex Resistance For Puncture Resistant Devices (ASTM F2412-18a, 11.7 & CSA Z195-14, 6.3.2)

		<u>ASTM F2413-18 Requirement</u>	<u>Pass/Fail</u>
Left:	No Signs Of Cracking After 1.5 x 10 <sup>6</sup> Flexes.	*	Pass
Right:	No Signs Of Cracking After 1.5 x 10 <sup>6</sup> Flexes.	*	Pass
Right:	No Signs Of Cracking After 1.5 x 10 <sup>6</sup> Flexes.	*	Pass

Remark: \* = No Signs Of Cracking After 1.5 x 10<sup>6</sup> Flexes.



*End Of Report*

*This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. No copy of the test report(except for full text copy) shall be made without the written approval by Intertek.*