



Number: GZHT90871529

Date: Mar 22, 2019

Applicant: CORTINA N.V.

MEERSBLOEM-MELDEN 42, 9700 OUDENAARDE,BELGIUM

Attn: PETER DE MEZURE

Sample Description:

Four and a half (4.5) pairs of submitted samples said to be Steel plates.

Standard : ASTM F2413-18

Size : US 9

Buver's Name : CORTINA N.V.

Ref. No : SAFETYBOY/SAFETYRUN/SAFETYBOY2/SAFETYRUN2/X0600

Brand : SAFETYJOGGER
Manufacturer : CORTINA N.V.
Colour : BLK/GRY

Vendor : -Supplier : -P.O. No. : --

Ref. : Steel plate used for SAFETYBOY/SAFETYRUN/SAFETYBOY2/SAFETYRUN2/

X0600

Country Of Origin : --

Goods Exported To : Belgium/U.S.A. Date Received/Date Test Started: Mar. 15, 2019

Date Final Information Confirmed: --

Test Result Please Refer To Attached Page(S).

Should you have any query on this report, you may contact at gzfootwear@intertek.com

Authorized By:

For Intertek Testing Services Shenzhen Ltd.

Guangzhou Branch

Guiliang Dong Senior Lab Manager

Page 1 Of 3

er / nicoleho

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司 #01/E501/E601/E701/E801, 3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路 7 号之二第 1—8 层 02 房、01 房 101、E201、E301、E401、E501、E601、E701、E801

China 中国广州经济技开发区开发大道 235 号恒运大厦 3 楼

Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663

中国)州经济仅开及区开及人组 233 与但运入厦 3 校 Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730

Economic & Technological Development District, Guangzhou,







Number: GZI

GZHT90871529

TEST REPORT

Tests Conducted (As Requested By The Applicant)

1 Puncture Resistance Footwear (PR) (ASTM F2412-18a, 11, Conditioned At 22°C And 50% RH For 24 h And Testing Performed At The Same Conditions.)

		ASTM F2413-18	Pass/Fail
		Requirement	_
	The Test Pin Did Not Penetrate Beyond	Min. 1 200 N (*)	Pass
Left:	The Face Of The Material Nearest The		
	Foot Before 1 200 N.		
	The Test Pin Did Not Penetrate Beyond	Min. 1 200 N (*)	Pass
Right:	The Face Of The Material Nearest The		
	Foot Before 1 200 N.		
	The Test Pin Did Not Penetrate Beyond	Min. 1 200 N (*)	Pass
Right:	The Face Of The Material Nearest The		
-	Foot Before 1 200 N.		

Remark: \* = The Test Pin Does Not Visually Penetrate Beyond The Face Of The Material Nearest The Foot.

2 Corrosion Resistance For Puncture Resistant Plates (ASTM F2412-18a, 11.8 & ASTM B117, 5% NaCl Solution For 24 Hours)

		<u>ASTM F2413-18</u>	Pass/Fail
		<u>Requirement</u>	
Left:	No Sign Of Corrosion.	*	Pass
Right:	No Sign Of Corrosion.	*	Pass
Right:	No Sign Of Corrosion.	*	Pass

Remark: \* = No Sign Of Corrosion, De-lamination, Or Deterioration.

3 Flex Resistance For Puncture Resistant Devices (ASTM F2412-18a, 11.7 & CSA Z195-14, 6.3.2)

		ASTM F2413-18	Pass/Fail
		<u>Requirement</u>	
Left:	No Signs Of De-lamination Of Layers Or Cracking After 1.5 x 10 <sup>6</sup> Flexes.	*	Pass
Right:	No Signs Of De-lamination Of Layers Or Cracking After 1.5 x 10 <sup>6</sup> Flexes.	*	Pass
Right:	No Signs Of De-lamination Of Layers Or Cracking After 1.5 x 10 <sup>6</sup> Flexes.	*	Pass

Remark: \* = No Signs Of De-lamination Of Layers Or Cracking After 1.5 x  $10^6$  Flexes.

/ nicoleho

Page 2 Of 3

深圳天祥质量技术服务有限公司广州分公司

Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路 7 号之二第 1—8 层 02 房、01 房 101、E201、E301、E401、E501、E601、E701、E801

Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663

Economic & Technological Development District, Guangzhou, China

中国广州经济技开发区开发大道 235 号恒运大厦 3 楼

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730





Number: GZHT90871529



End Of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. No copy of the test report(except for full text copy) shall be made without the written approval by Intertek.

/ nicoleho

Page 3 Of 3

深圳天祥质量技术服务有限公司广州分公司

Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路 7 号之二第 1—8 层 02 房、01 房 101、E201、E301、E401、E501、E601、E701、E801

中国广州经济技开发区开发大道 235 号恒运大厦 3 楼

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730

Economic & Technological Development District, Guangzhou,