

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

198 Ke Zhu Road, Science Park, Economic & Technology Development Zone, Guangzhou, China

Tel: +86-20-8215 5555 Fax: +86-20-8215 5189 Ref No: SL92209231256401 Issued date: February 11,2022

Certificate of Conformance

Manufacturer: CORTINA N.V.

Style Name: SAFETY STAR S3 LOW(SI110019A) / SAFETYSTAR

Style or PO Number: SAFETY STAR S3 LOW(SI110019A) / SAFETYSTAR

Buyer/Brand: SAFETY JOGGER

It is confirmed that the submitted said product meets the performance requirements of ASTM Specification F2413-18 as tested in accordance with ASTM Test Methods F2412-18a. The safety hazard(s) tested are listed below:

Safety Hazard(s)	Report Number	Issued Date	Test Result
Impact Resistant (I)	SL92119337192901FW	January 17,2022	Pass
Compression Resistant (C)	SL92119337192901FW	January 17,2022	Pass
Static Dissipative Performance (SD 10)	SL92209231256401FW	February 11,2022	Pass
Puncture Resistance Plate* (PR) - Puncture Resistance	SL92119337192901FW	January 17,2022	Pass
Puncture Resistance Plate* (PR) - Flexing	SL92119337192901FW	January 17,2022	Pass
Puncture Resistance Plate* (PR) - Corrosion	SL92119337192901FW	January 17,2022	Pass

This Certificate of Conformance must be used together with the associated test report(s) listed above.

Asan_Huang

Technical Manager

Softline laboratory

